



# PhilGEPS

Philippine Government Electronic Procurement System

Central Portal for  
Philippine Government  
Procurement Opportunities

## Bid Notice Abstract

### Request for Quotation (RFQ)

Reference Number 6761421  
 Procuring Entity OFFICE OF THE PRESIDENT  
 Title RFQ / 19-10-1070 / PROCUREMENT OF AIRCON REPAIR FOR VARIOUS O.P. SERVICE VEHICLES  
 Area of Delivery Metro Manila

<b>Solicitation Number:</b>	19-10-1070	<b>Status</b>	In-Preparation
<b>Trade Agreement:</b>	Implementing Rules and Regulations	<b>Associated Components</b>	1
<b>Procurement Mode:</b>	Negotiated Procurement - Small Value Procurement (Sec. 53.9)	<b>Bid Supplements</b>	0
<b>Classification:</b>	Goods	<b>Document Request List</b>	0
<b>Category:</b>	Vehicle Repair and Maintenance	<b>Date Published</b>	17/12/2019
<b>Approved Budget for the Contract:</b>	PHP 353,200.00	<b>Last Updated / Time</b>	16/12/2019 10:04 AM
<b>Delivery Period:</b>	3 Day/s	<b>Closing Date / Time</b>	24/12/2019 17:00 PM
<b>Client Agency:</b>			
<b>Contact Person:</b>	Sonny Boy Bautista Berbano Presidential Staff Assistant Procurement Unit, Rm 123 Mabini Hall Bldg., J.P. L Malacañang Complex, San Miguel Manila Metro Manila Philippines 1005 63-2-7844286 Ext.4601 63-2-7844286 procurement_unit@malacanang.gov.ph		

#### Description

##### A) REQUEST FOR QUOTATION

##### ISUZU CROSSWIND ZGP 367 / SHG 410

1. 1 lot Aircon Repair: Pulldown Evaporator & Cleaning (Front & Rear), Leak Testing & Vacuum of System, Recharging of Freon Gas 134A & Labor

Parts to be replaced:

2. 1 pc Evaporator (Front)
3. 1 pc Evaporator (Rear)
4. 2 pcs Expansion Valve (Front & Rear)
5. 1 pc Receiver Drier

6. 1 lot Reconditioning of Clutch Fan (Silicon Oil).

NISSAN FRONTIER SFN 518 (Assigned to Engineering Office)

7. 1 lot Aircon Repair: Pulldown Evaporator & Gen. Cleaning, Leak Testing & Vacuum, Recharging of Freon Gas 134A & Labor

Parts to be replaced:

8. 1 pc Compressor
9. 1 pc Expansion Valve
10. 1 pc Receiver Drier
11. 1 pc Blower Motor
12. 1 pc Thermostat
13. 1 lot Flushing of System

HYUNDAI GRAND STAREX ZTZ 252 / SJN 651

14. 1 lot Aircon Repair: Pulldown Dashboard & Evaporator for Gen. Cleaning of Aircon System, Leak Testing & Vacuum, Recharging of Freon Gas 134A & Labor

Parts to be replaced:

15. 2 pcs Expansion Valve (Front & Rear)
16. 1 pc Receiver Drier
17. 1 pc Thermostat
18. 1 pc Cabin Filter

HYUNDAI GRAND STAREX ZTZ 255 / SJN 721

19. 1 lot Aircon Repair: Pulldown Dashboard & Evaporator for Leak Testing & Vacuum of Aircon System, Recharging of Freon gas 134A & Labor

Parts to be replaced:

20. 2 pcs Expansion Valve (Front & Rear)
21. 1 pc Receiver Drier
22. 1 pc Cabin Filter

TOYOTA INNOVA ZTR 287 / SJG 831 (Assigned to NCWC)

23. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen. Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon Gas 134A & Labor

Parts to be replaced:

24. 1 pc Compressor
25. 1 pc Evaporator (Front)
26. 1 pc Evaporator (Rear)
27. 2 pcs Expansion Valve (Front & Rear)
28. 1 pc Receiver Drier
29. 1 pc Cabin Filter
30. 1 pc Flushing of System

31. 1 pc Clutch Fan Recondition (Silicon Oil)

TOYOTA INNOVA ZTR 282 / SJG 832

32. 1 lot Aircon Repair: Pulldown Compressor & Evaporator (Front & Rear)

For Gen. Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon Gas 134A & Labor

33. 1 pc Compressor
34. 1 pc Evaporator (Front)
35. 1 pc Evaporator (Rear)
36. 2 pcs Expansion Valve (Front & Rear)
37. 1 pc Receiver Drier
38. 1 pc Cabin Filter
39. 1 lot Flushing of System

40. 1 lot Clutch Fan Recondition (Silicon Oil)

TOYOTA INNOVA ZGP 358 / SHU 968

41. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen. Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon Gas 134A & Labor

Parts to be replaced:

42. 1 pc Evaporator (Front)
43. 1 pc Evaporator (Rear)
44. 2 pcs Expansion Valve (Front & Rear)
45. 1 pc Receiver Drier
46. 1 pc Cabin Filter

47. 1 lot Clutch fan Reconditioning (Silicon Oil)

TOYOTA INNOVA UIU 608 / SKW 447 (Assigned to OSAP)

48. 1 lot Aircon Repair: Pulldown Compressor & Evaporator (Front & Rear)  
For Gen. Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon Gas 134A & Labor
49. 1 pc Compressor
50. 1 pc Evaporator (Front)
51. 1 pc Evaporator (Rear)
52. 2 pcs Expansion Valve (Front & Rear)
53. 1 pc Receiver Drier
54. 1 lot Flushing of System
55. 1 pc Cabin Filter
56. 1 lot Clutch Fan Recondition (Silicon Oil)  
TOYOTA INNOVA ZDA 931 / SHB 421
57. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen.  
Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon Gas 134A & Labor
58. 1 pc Evaporator (Front)
59. 1 pc Evaporator (Rear)
60. 2 pcs Expansion Valve (Front & Rear)
61. 1 pc Receiver Drier
62. 1 pc Cabin Filter
63. 1 lot Clutch Fan Reconditioning (Silicon Oil)  
TOYOTA INNOVA ZTR 281 / SJG 826
64. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen.  
Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon of Gas 134A & Labor
- Parts to be replaced:
65. 1 pc Evaporator (Front)
66. 1 pc Evaporator (Rear)
67. 2 pcs Expansion Valve (Front & Rear)
68. 1 pc Cabin Filter
69. 1 pc Receiver Drier
70. 1 pc Compressor
71. 1 lot Flushing of System
72. 1 lot Clutch Fan Reconditioning (Silicon Oil)  
TOYOTA INNOVA ZDA 933 / SHB 441
73. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen.  
Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon of Gas 134A & Labor
- Parts to be replaced:
74. 1 pc Evaporator (Front)
75. 1 pc Evaporator (Rear)
76. 2 pcs Expansion Valve (Front & Rear)
77. 1 pc Receiver Drier
78. 1 pc Cabin Filter
79. 1 lot Clutch Fan Reconditioning (Silicon Oil)  
TOYOTA INNOVA PDQ 708 / SJS 168
80. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen.  
Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon of Gas 134A & Labor
- Parts to be replaced:
81. 1 pc Evaporator (Front)
82. 1 pc Evaporator (Rear)
83. 2 pcs Expansion Valve (Front & Rear)
84. 1 pc Receiver Drier
85. 1 pc Cabin Filter
86. 1 pc Clutch Fan Reconditioning (Silicon Oil)  
ISUZU ELF SKX 963 (Assigned to Engineering Office)
87. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen.  
Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon of Gas 134A & Labor
- Parts to be replaced:
88. 1 pc Compressor
89. 1 pc Expansion Valve
90. 1 pc Receiver
91. 1 lot Flushing of System  
ISUZU ELF SKX 964 (Assigned to Assets Management Office)
92. 1 lot Aircon Repair: Pulldown Evaporator (Front & Rear) for Gen.  
Cleaning of A/C System, Leak Testing & Vacuum, Recharging of Freon of Gas 134A & Labor
- Parts to be replaced:
93. 1 pc Compressor
94. 1 pc Expansion Valve
95. 1 pc Receiver
96. 1 lot Flushing of System

Delivery Period: Three (3) Working Days / Vehicle

**B) USE COMPANY LETTERHEAD FOR YOUR QUOTATION & ADDRESS TO:**

DIR. JAMES JUPER B. AGUILAR  
Head, Procurement Unit  
Office of the President  
M-123 Mabini Hall, J.P. Laurel St.,  
Malacañang Complex,  
San Miguel, Manila

Tel Number: (02) 784-4286 loc. 4601  
Fax Number: (02) 784-4286 local 4709  
Email Address:  
procurement\_unit@malacanang.gov.ph  
op.procurementunit@gmail.com

**C) ELIGIBILITY DOCUMENTS MUST BE ATTACHED TO THE QUOTATION**

1. Latest/updated/valid PhilGEPS Registration Certificate
2. Latest/valid Mayor's Permit
3. TIN

**Note:**

- Kindly Attach the Complete Eligibility Documents to Avoid DISQUALIFICATION.
- Include the BACK PAGE OF THE MAYOR'S/BUSINESS PERMIT if Available
- Scan the Documents in a manner that the entries are legible/readable.

**D) INDICATE IN YOUR QUOTATION THE FOLLOWING**

1. Terms of Payment:
2. Warranty:
3. Place of Delivery:
4. Delivery Period:
5. Price Validity Period:
6. Stock Availability:
7. Certificate of Exclusive Distributorship, if any
8. Brand

**Created by** Sonny Boy Bautista Berbano

**Date Created** 16/12/2019

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.